

# FIELD INSPECTION REPORT

| Date of Inspection:                         | 16/12/20                                                                                                                                | District:   | Darbhanga |
|---------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-------------|-----------|
| Division:                                   | Bircul                                                                                                                                  | Length(Km): | 1.4 to 24 |
| Name of Road:                               | Middle School Jagasu to Jagasu West (Hilly)                                                                                             |             |           |
| Scheme/Programme:                           | Maintenance                                                                                                                             |             |           |
| Package No.                                 |                                                                                                                                         | Road Id No. |           |
| Status of the Project:                      | Ongoing / Completed/ Under Maintenance                                                                                                  |             |           |
| Work is a case of:                          | New Connectivity/Up gradation/ Maintenance                                                                                              |             |           |
| S No.                                       | Parameters to be Checked                                                                                                                | Remarks     |           |
| 1                                           | <b>Pavement</b>                                                                                                                         | ✓           |           |
| a)                                          | Road Junction condition                                                                                                                 | S/U         |           |
| b)                                          | Condition of Surfacing                                                                                                                  | ✓ S/U       |           |
| c)                                          | Riding Quality                                                                                                                          | S/U ✓       |           |
| d)                                          | Road Camber                                                                                                                             | ✓ S/U       |           |
| e)                                          | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                                             | ✓ Yes/No    |           |
| f)                                          | Contraction Joints provided or not (CC Pavement)                                                                                        | ✓ Yes/No    |           |
| g)                                          | Compaction of flank /slope & raincuts if any                                                                                            | ✓ Yes/No    |           |
| 2                                           | <b>Cross Drainage</b>                                                                                                                   |             |           |
| a)                                          | Condition of head walls in Hume pipe culverts including its painting                                                                    | ✓ S/SRI/U   |           |
| b)                                          | Condition of Abutment & Wing walls Slabs in RCC culverts                                                                                | ✓ S/SRI/U   |           |
| c)                                          | Condition of railing /slabs/ approach for Bridges                                                                                       | S/SRI/U     |           |
| 3                                           | <b>Road Furniture</b>                                                                                                                   |             |           |
| i)                                          | Whethersign boards/ informatory/ caution Board / Km & 200m stones/ Pavement road markings are provided and maintained - Repairing work. | ✓ Yes/No    |           |
| 3                                           | <b>Compliance History</b>                                                                                                               |             |           |
| j)                                          | Status of ATR's & any others                                                                                                            |             |           |
|                                             | Note - Above road damaged from flood.                                                                                                   |             |           |
| Overall Rating:                             |                                                                                                                                         |             |           |
| Satisfactory (S)                            |                                                                                                                                         |             |           |
| Satisfactory but requires Improvement (SRI) |                                                                                                                                         | SRI         |           |
| Unsatisfactory (U)                          |                                                                                                                                         |             |           |

  
 Name: - Vijay Kumar Jha  
 Designation: JE/IC/Divisional Engineer

16/12/20  
 AS

(Signature)

Scanned by CamScanner