FIELD INSPECTION REPORT

Date of	Inspection:	11.12.20 Dis	trict: Maulhubani	
Division: Janger Length (km):			igth (km):	
		MAINTENANCE V		
Scheme	Programme:			
Puckage No.: Bear Ray Road Id No.:				
	Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks		
SI. No.		Parameters to be checked Remarks		
1.	Pavement			
a)	Road Junction condition			√s/U
b)	Condition of Surfacing			/\$/ U
c)	Riding Quality			√s/U
d)	Road Camber			√s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			~Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2,	Cross Drainag	e in the law to the		
a)	Condition of head walls in Hume pipe culverts including its painting			√s/sri/U
b) -	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Cilento			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No/
4	Compliance H	Say -		Alleria appendina - alle
a)	Status of ATR'	s & any others	343-4-3-8856	M
				1

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRS
Unsatisfactory (U)	

NAME: Silier Kr. Jumes
DESIGNATION: 12