		FIELD INSPE	CTION REPORT		
Date of	Inspection: /	7.12.2020	District: Mackybani		
					· · · · · ·
Name of	f the Road: S	dhapkala kachh	Length (km): 1-827 F	probsy Road	Kac441 Bay ray
Scheme	Programme:	MAINTENANCE			chayk-talk
Package No.:			Road Id No.:		
Status of the Project: Ongoing/Completed		/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.	A STATE OF THE PARTY OF THE PAR	Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction	ction condition			
b)	Condition of Surfacing			S/U	

c)	Riding Quality				
d)	Road Camber	Š/U			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any				
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges				
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No			
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

MIA

HIA

NAME: Scholoo Churchery
DESIGNATION: 7-6