

## FIELD INSPECTION REPORT

Date of Inspection: 18/12/20		District: JEHANABAD
Division: Jehanabad		Length (km): 1.424 Km
Name of the Road: Lohs-Murasa to Guhribigha		
Scheme/Programme: PMGSY		MAINTENANCE
Package No: BR/GR-347		Road Id No.:
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	

S.N	Parameters to be checked	Remarks
1.	Payment	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME:

DESIGNATION:

Binaad Kumar  
AE

Signature  
18/12/20