

FIELD INSPECTION REPORT

Date of Inspection :	17/12/2020	District:	Nalanda
Division :	Rajgir	Length (km):	28 K.M.
Name of the Road:	Andws Dharahara Road to Ajadnagr		
Scheme/Programme:	MAINTENANCE	MNP-4515	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (N/A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (N/A)
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ☒
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign ☒ boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m NOTE maintained ☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I
Unsatisfactory (U)	

Rambhresh Kumar
SE.
NAME: Rajgir

17/12/20
(Signature)