FIELD INSPECTION REPORT

Date of Inspection :			District: Rohta			
Division: Dehzi			Length (km): 0.205 Km			
Name of the Road: Road to Mathia tola						
Scheme/Programme: MAINTENANCE						
Package No.: Road Id No.:						
Status of the Project: Ongoing/Completed/Under Maintenance						
	Vork is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	Parn	Parameters to be checked			Remarks	
1.	Pavement					
а)	Road Junction condition			-S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			S/U		
d)	Road Camber			_ S/U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			/Ycs/No		
f)	Contraction Joints provided or not (CC Pavement)-			Yes/No		
g)	Compaction of flank/slope & raincuts if any			/ Yes/No		
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCE culverts			S/SRI/U		
c)	Condition of milings/slab/approach for Bridges			S/SRI/U		
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
4.	Compliance History					
a)	Status of ATR's & any oth	ers				

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	* "

(Signature) 20

NAME: On Prakowsh Kuman

DESIGNATION: Je