FIELD INSPECTION REPORT

Date of 1	nspection :	16/12/2020	District: Bhofpyr	
Division	: PIK	20	Length (km): / 1.20	
Name of	the Road:	L047 - L030	to Balihari (VR47)	
Scheme/	Programme:	MAINTENANCE		
Package		07R-310	Road Id No.:	
Status of the Project:			mpleted/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenan		/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks	
1.	Payement			
a)	Road Junction condition			√\$/U
b)	Condition of Surfacing			S/UV
c)	Riding Quality			√8/U
d)	Road Camber			√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drains	ge		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRA/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Read Furnitu	ire .		<u> </u>
a)	Whether sign stones/Paveme	boards/informator ent road markings a	ry/cautionary Board/km & 200m re provided and maintained	Yes/No
4	Compliance I	listery		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (\$RI)	
Unsatisfactory (U)	U

(Signature)

ATR

NAME: Usnesh Chaughory
J.E.

Status of ATR's & any others

(i)	Rectification done or Not?	Not
(ii)	Work Started or Not?	Not
(iii)	Notice issue by PIU or Not?	yes
(iv)	Rectification Started or Not?	Not
(v)	Comment if Any?	
(vi)	Grade	U
(vii)	Upload image (max 5 image)	Yes
(viii)	Upload inspection Report PDF format	yes

In 1200