

# FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District: Nalanda
Division : Rajgir		Length (km):
Name of the Road: Arayan bhaire sima se bhondar Kona Parbat Pur benifal		
Scheme/Programme: MAINTENANCE		4515
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		✓
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Gross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement: (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION: