

FIELD INSPECTION REPORT

Date of Inspection : 12-12-20		District: Gaya		
Division : Gaya		Length (km):		
Name of the Road: L082-Dumraon To Mahugain				
Scheme/Programme: MAINTENANCE		Road Id No.:		
Package No.: BR-2R-975		Ongoing/Completed/Under Maintenance ✓		
Status of the Project:		New Connectivity/Up gradation/ Maintenance		
Work is a case of:				
SL No.	Parameters to be checked			Remarks
1.	Pavement			✓ S/U
a)	Road Junction condition			✓ S/U
b)	Condition of Surfacing			✓ S/U
c)	Riding Quality			✓ S/U
d)	Road Camber			✓ Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)			✓ Yes/No
g)	Compaction of flank/slope & raincuts if any			
Condition of Culverts				
a)	Condition of head walls in Hume pipe culverts including its painting			✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			✓ S/SR/U
c)	Condition of railings/slab/approach for Bridges			✓ S/SR/U
Condition of Road				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓ Yes/No
Status of ATR's & any others				
a)				NA

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chandra Chatter Karmar

DESIGNATION: Jt

12-12-20
(Signature)