

FIELD INSPECTION REPORT

Date of Inspection:	17/12/2020	District:	Bhagalpur
Division:	Kahalgaon	Length (km):	1.01 km
Name of the Road:	L086-Pakriya Road to Jogiya Talab (BR-06R-341)		
Scheme/Programme:	MAINTENANCE	PMGSY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
SL No.	Particulars		
1.	Pavement		
a)	Road Junction Condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (GC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Crossing		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
i)	Status of ATR's & any others	No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	RI
Unsatisfactory (U)	

70m Flank damaged in Flood.


 17/12/2020
 (Signature)

NAME: