

FIELD INSPECTION REPORT

p/penhti

Date of Inspection:	16/12/2020	District:	Bhargalpur
Division:	Kabalgan	Length (km):	1.320 km
Name of the Road:	2055 Bilaiya to Sarkanda (UR 38) BR-06R-345		
Scheme/Programme:	MAINTENANCE	PMUSY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance		
S. No.	Parameter/Spot/Channel	Remarks	
1.	Pavement		
a)	Road Junction Condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross-drainages		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
i)	Status of AFR's & any others		NO

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Flank damage in some portion

16/12/2020
(Signature)

NAMU: