

FIELD INSPECTION REPORT

pirpanti

Date of Inspection:	18/12/2020	District:	Bhagalpur						
Division:	Kahalgau	Length (km):							
Name of the Road:	Lot 21 Madhopur TOI to Parsurampur (BR-06R-344)								
Scheme/Programme:	MAINTENANCE	pmcsc							
Package No.:		Road Id No.:							
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance								
Work is a case of:	New Connectivity/Up gradation/Maintenance								
Sl. No.									
1.	Pavement								
a)	Road Junction Condition	S/U	S						
b)	Condition of Surfacing	S/U	S						
c)	Riding Quality	S/U	S						
d)	Road Camber	S/U	S						
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No	No						
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA						
g)	Compaction of flank/slope & raincuts if any	Yes/No	No						
2.	Crossing Bridges								
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S						
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA						
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA						
3.	Road Furniture								
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes						
4.	Compliance History								
i)	Status of AFR's & any others	No							
Overall Rating:	<table border="1"> <tr> <td>Satisfactory (S)</td> <td>S</td> </tr> <tr> <td>Satisfactory but requires Improvement (SRI)</td> <td></td> </tr> <tr> <td>Unsatisfactory (U)</td> <td></td> </tr> </table>			Satisfactory (S)	S	Satisfactory but requires Improvement (SRI)		Unsatisfactory (U)	
Satisfactory (S)	S								
Satisfactory but requires Improvement (SRI)									
Unsatisfactory (U)									

On 18/12/2020

(Signature)