

pirpanti

FIELD INSPECTION REPORT

Date of Inspection: 16/12/2020		District: Bhagalpur	
Division: Kailashpur		Length (km):	
Name of the Road: 2034- Upper Bhalaria to Jades Bhalaria (VR14)		BR-06R-343	
Scheme/Programme: MAINTENANCE		pm 457	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.			
1. Pavement			
a)	Road Junction condition	S/S	S
b)	Condition of Surfacing	S/S	S
c)	Riding Quality	S/S	S
d)	Road Camber	S/S	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NO
2. Cross-drainages			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U	NA
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4. Compliance History			
a)	Status of ATR's & any others	Yes	
Overall Rating: ATR points are verified and checked by SEM.			
Satisfactory (S)		S	
Satisfactory but requires Improvement (SR)			
Unsatisfactory (U)			

16/12/2020
(Signature)

NAME: