

# FIELD INSPECTION REPORT

Date of Inspection: 16-12-2020		District: BANKA
Division: BANKA-2		Length (km): 2.90
Name of the Road: Loge to Dayalpur (BR03R-464) PMUSY		
Scheme/Programme: MAINTENANCE, 2nd year		
Package No.:		Road Id No.: 20703602229
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U M/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U M/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

*Ajay*  
16-12-2020  
(Signature)

NAME: AJAY KUMAR  
DESIGNATION: AE