

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District : Mungers
Division : Mungers		Length (km): 3.180
Name of the Road : T01 to Gosaichak		
Scheme/Programme : MAINTENANCE PMUSY		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl.No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S / U
b)	Condition of Surfacing	✓ S / U
c)	Riding Quality	✓ S / U
d)	Road Camber	✓ S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes / No
f)	Contraction Joints provided or not(CC Pavement)	✓ Yes / No
g)	Compaction of flank/slope & raincuts if any	✓ Yes / No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges — N/A	S / SRI / U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes / No
4	Compliance Histroy	
a)	Status of ATR's & any others — one hume pipe damage	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI) ✓	
Unsatisfactory (U)	

NAME :

DESIGNATION :

(Signature)
16/12/2020
Munger
A-E

2