

FIELD INSPECTION REPORT

Date of Inspection :-	Khasara	District :-	Khasara
Division :-	Khasara	Length (Km) :-	0.490
Name of Road :-	Anaiya Gharani pfo path to perchurati rda Gharani Jan Waa Kali Pithan		
Scheme/Programme :-	HHGSY	Maintenance	
Package No. :-	-	Road ID No. :-	
Status of Project :-	Under Maintenance	Ongoing/Complete/Under Maintenance	
Work is a case of :-	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. ✓	Yes/No ✓
f)	Constrution Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any ✓	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

17.12.20
JE/Mam
(Signature)