

FIELD INSPECTION REPORT

DATE OF INSPECTION :		DISTRICT	SUPAUL
DIVISION : THIVENIGANI		LENGTH (Km)	2.50 km
NAME OF ROAD : L-02 th Churni To Sahpur (VR 20)			
SCHEME PROGRAMME		MAINTENANCE	
PACKAGE NO. BR 35 R 132		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/Maintenance	
Sl. No.	PARAMERERS TO BE CHECKED		REMARKS
1	PAVEMENT		
a	Road junction condition		S/U
b	Condition of Surface		S/U
c	Riding Quality		S/U
d	Road Camber		S/U
e	Whether free from defectssuch as visible cracks exposed aggregates in case of CC pavement		Yes/No
f	Construction Joints provided or not (CC Pavement)		Yes/No
g	Compaction of flank/ Slope & Rain cuts if any		Yes/No
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained		✓ Yes/No
3	Compliance History		
a	Status of ATR's & any Others		Yes/No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement	
Unsatisfactory (U)	

Syandra Kumar
SDO RWT
Chhatapur
Name

Syandra Kumar
16/12/20
Signature