## FIELD INSPECTION REPORT

	ite of Inspection:  6 *	12-20 District: Katikov	
Name of Road: Scheme/ Programme:		LOSS TO CHARRAMARI	
		MAINTENANCE	
Pac	kage No. 88168_315		+
Status of the Project: Work is a case of:		Onging/Completed/Under Maintenance	
1	Pavement	Parameters to be Checked	Remarks
n)	Read Junction Co.	ndition	
6)	Condition of Surfa	scing	SAU
c)	Riding Quality		™S/U
d)	Road Camber		VS/II
c)	Whether free from CC Pavement	defects such as visible cracks, exposed aggregates in case of	VS/U Ves/No
f)	Contraction Joints	provided or not (CC Pavement)	C-Strategy
g)	Compaction of flan	ik/slpoe & raincuts if any	Yes/No
2	Cross Drainage		VYes/No
3)	Condition of headw	valls inn Humepipe culverts including its painting	The state of the s
6)	Condition of Abutn	nent & Wings walls, Slab in RCC culverts	S/SRI/U
:)		s/slabs//approach for Bridges	S/SRI/U
	Road Furniture		S/SRI/U
	Whether sign board road markings are p	s/informatory/cautionary Board/Km & 200m stone/ Paver rovided and maintained.	ment Yes/N
1	Compliance Histor	y	MAN TO SERVE SERVE
15	Status of ATR & an	v others	No

Overall Grading: S

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

(Signature)

Name: Shiv Norvayor Mandal Degisnation AE