FIELD INSPECTION REPORT

Date of	Inspection: 16:17	1.20	District: Kick Fi hari	7	
Name of Road:		To3 To BALDA			
Scheme/ Programme:		MAINTENANCE			
Packag	eNo. BRIGR-	335	Road ID No.		
Status of the Project:		Onging	Onging/Completed/Under Maintenance		V
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance			1
SLNo			Parameters to be Checked	Remarks	1
1	Pavement				A
a)	Road Junction Co	The state of the s		S/U	4
b)	Condition of Surfacing		~S/U	_	
c)	Riding Quality			~STU	1
d)	Road Camber			Yes/N	1=
e)	CC Pavement			1	Man
f)	Contraction Joints provided or not (CC Pavement)			Nesl	
g)	Compaction of flank/slpoe & raincuts if any				No
2	Cross Drainage			1 .60	
a)	Condition of headwalls inn Humepipe culverts including its painting		- 100	S/SRI/U	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		-		
c)	Condition of railings/slabs//approach for Bridges				SKI
3	AND DESCRIPTION OF THE PARTY OF	ASSESSED BY A PARTY OF THE PART		mant	7
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.				Yes
4	Compliance History				H
a)	Status of ATR & any others				
47	Parameter Control				
11.6	rading:	Sati	sfactory (S)	1	110
erali C	irading: S	Cati	sfactory but requires Improvement(SRI)		

Name: Shiv Harrayan mandel
Degisnation ArE, PWDUW) Sub-Bir Andabad

Unsatisfactory (U)

(Signature) 12.20