

FIELD INSPECTION REPORT

Date of Inspection: - 17.12.20		District: Kishanganj	
Division: Kishanganj-1		Length(km): 2.455 K.M	
Name of the Road: - L024 TO Panhatgaur			
Scheme/Programme: PMGSY			
Package No.: BR-18R-176		Road Id No.: 21205802118	
Status of the Project: Ongoing/Completed /Under Maintenance			
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation / <input type="checkbox"/> Maintenance			
Sl. No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No	
f)	Contraction Joints Provided or not (CC Pavement) N.A	Yes/No	
g)	Compaction of flank / slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR	

Overall Rating :

Satisfactory(S)	-S-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

Remarks - Road Ch- 1.750 TO 2.10 has been shoulder damage in bank of Bhatavari river due to last year flood and at some places pot and patches developed in this area


 17.12.20
 J.E

NAME: Radheshyam Prajapati

R.W.D (W) Division
Kishanganj-1