


FIELD INSPECTION REPORT

Date of Inspection: 18-12-2020		District: KISHANGANJ	
Division: KISHANGANJ-1		Length(km): 1.037	
Name of the Road: L061 - L062 to Gargaon			
Scheme/Programme: PMGSY			
Package No.: BR18R-183		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing 80m Surface Damage near Culvert due to Flood 2020		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of flank / slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts - NA		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges - NA		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others No Pending ATR		

Overall Rating :

Satisfactory(S)	"S"
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

NAME: RAMANUJ KUMAR
DESIGN : ASSISTANT ENGINEER


 18/12/2020
 R.W.D (W) Division
 Kishanganj-1
 SUB DIV : BAHADURGANT