

FIELD INSPECTION REPORT


Date of Inspection:- 17.12.20		District:- Kishanganj	
Division: Kishanganj-I		Length(km): 2.00 K.M	
Name of the Road: T02 TO Dahraon			
Scheme/Programme: PMGSY			
Package No.: BR-18R-184		Road Id No.: 21205802131	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		<input checked="" type="checkbox"/> New Connectivity/ Up gradation / Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	S/U✓	
c)	Riding Quality	S/U✓	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank / slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History	-	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-U-

Remarks - At ch-0.600 to 1.00 km Road had been badly effected and damaged due to last year flood.

NAME: Radheshyam prajapati


 J.E.
 17.12.20
 R.W.D (W) Division
 Kishanganj-1