## FIELD INSPECTION REPORT

Date of Inspection :	10.12.2020 Distr	rict: SIWAN
Division: MAHAE		gth (km): 2100 m
Name of the Road: 10	34 Pandit ke Rampur	BI road TO3 to badarzamin
Scheme/Programme:	MAINTENANCE PMGSY	
Package No.:		d Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
	A STREET OF THE PROPERTY OF TH	

ork is a case of: New Connectivity/Op graduation vicinities		Remarks	
sl. No.	Parameters to be checked	Table Mail	
i,	Pavement	\$/U	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
	Contraction Joints provided or not (CC Pavement)	Yes/No	
n)	Compaction of flank/slope & raincuts if any	Yes/No	
g)			
- 2,	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges 5/5R/70		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	age manife start i vider demonstration in comparing administration in the second	
a)	Status of ATR's & any others	The state of the s	

Overall Rating :

	C
Satisfactory (S)	
Satisfactory but requires Improve	ement (314)
Unsatisfactory (U)	

(Signature)

NAME: bharmendra kumar

77