FIELD INSPECTION REPORT

Date of Inspection :	17.12.20	District: Myzforpun_
Division: East -1		Length (km): 0.290
	033 To Puzbit	ola Sunderbuz.
Scheme/Programme:	MAINTENANCE	GT.SNY
Package No.:		Road Id No.: 3 1507218003
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	_S/U
b)	Condition of Surfacing	_S/U
c)	Riding Quality	∠S/U
d)	Road Camber	∠S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	√Yes/No
g)	Compaction of flank/slope & raincuts if any	A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	\ r S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts +A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	US/SRI/U
3.	Road Furniture	,
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

17.12.20

(Signature)

NAME: Ralceshicumar Rausham

DESIGNATION: JE