(51)

FIELD INSPECTION REPORT

Date of l	Inspection:	7.12.2020	District: MUZAFFAR	NR	
Division	: EAS	T-1	Length (km): 0.660 KM		
Name of	the Road: 70.	3 to paschim	Yadar tola.		
	Programme:	MAINTENANCE	91311		
Package			Road Id No.: 3150721	8004.	
			mpleted/Under Maintenance		
	a case of:		/Up gradation/ Maintenance		
SI. No.	*******	Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/W	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/Nov	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			NAS/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign stones/Paveme	boards/informatory ent road markings ar	y/cautionary Board/km & 200m e provided and maintained	Yes/No√	
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

1
10'
•
"U"

Ashutel Kun

(Signature)

NAME: ASHUTOSH KUMAR

DESIGNATION: JE-SAICAA