

FIELD INSPECTION REPORT

Date of Inspection:	16/12/2020	District:	Darbhanga
Division:		Length(Km):	2.766 Km
Name of Road:	Tatari to Kubaal		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank /slope & raincuts if any	Yes/No ✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U ✓
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U ✓
3	Road Furniture	
i)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓
	Compliance History	
j)	Status of ATR's & any others	
	Note - Above road submised in Road 2020	

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name: *Vijay Kumar Jha*
 Designation: *Jr. El. Kuch & Khand.*

(Signature)

16/12/20
A-E

Scanned by CamScanner

Scanned with CamScanner