## FIELD INSPECTION REPORT

nte of I	nspection:	1/12/2020	District: Patma.	-
ivision: Palis				A /40 1
ime of	the Rond: Ac	hok Raugné		0.600 King
	. objumilie:	MAINTENANCE	Shiv temples to Noul	natifur Maso
ckage			Road Id No.:	-
tatus of the Project: Ongoing/Comple  Vork is a case of: New Companion		ed/Under Maintenance	1 10	
No.	a case of:	New Connectivity	Up gradation/ Maintenance	-
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			LS/B
b)	Condition of Surfacing			SILV
c)	Riding Quality			SIN
d)	Road Camber			STV
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			d Yes/No NIA
1)	Contraction Joints provided or not (CC Pavement)			YesAVO HIA
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		the first
a)	Condition of head walls in Hume pipe culverts including its painting			g \8/SRIAU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			10 m
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			世紀本華原
a)	Status of ATR's & any others			No
-				
Overall Rating : Satisfactor		Satisfactory (5)		S
			t requires improvement (SR	1)
	- 1	Unsatisfactory	(U)	

NAME:

85 Rm.
17/12/2020
A.E

(Signature)