

FIELD INSPECTION REPORT

Date of Inspection: 17/11/2020 District: Muzaffarpur
 Division: RWD East-1 MAE Length (km): 1.37 km
 Name of the Road: Muzaffarpur Mahua path par pal to Gaudhiga Bishampur
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ No
f)	Contraction joints provided or not (CC Pavement)	✓ No
g)	Compaction of flank slope & ditches if any	Yes ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI
c)	Condition of railings/slab approach for Bridges	✓ SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Plan is damaged due to flood.
 Satisfactory (S) 5
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

NAME:

DESIGNATION:

K. Anurag
 17/11/2020
 (Signature)

AE, RWS
 K. Anurag