051	nspection: 14/12/20 District Property	
late Of I	nspection: 14/12/20 District: Siwan	
DIVISION.	I and I all all all all all all all all all a	
vame Of	the road:	
	riogramme:	
ackage		
tatus O	f the Project : Road Id No. :	
Vork is a	case of . Ongoing/Completed/Under Maintenance	9
l. No.	New Connectivity/Up gradation/ Ma	intenance
1	Parameters to be Checked Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	S/V
c)	Riding Quality	S/X
d)	Road Camber	S/Jd
	Whether free from defects such as visible cracks, exposed aggregates in	S/V
e)	case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	s/SRI/W
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	-
a)	Whether sign boards/informatory/cautionary Board/km & 200m	Yes/No
	stones/Pavement road markings are provided and maintained	
4	Compliance History	T
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	V

NAME:

ANAND KUMAR

DESIGNATION:

AE

(Signature)

MANISH KUMAR OJHA (J.E.)