

FIELD INSPECTION REPORT

Date Of Inspection : 14/12/20		District: Siwan	
Division: Mahrajganj		Length : 1.20 km	
Name Of the Road : 508 से पटल नदी			
Scheme/Programme :		GTJNY	
Package No. :		Road Id No. :	
Status Of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

NAME :
DESIGNATION :

ANAND KUMAR
AE

14/12/20
(Signature)

14/12/20
MANISH KUMAR OJHA (J.E.)