

FIELD INSPECTION REPORT

Date of Inspection:	17.12.2020	District:	Nalanda
Division:	H2189	Length (km):	
Name of the Road:	Yogipur Gogaihur to surat bigha via motibigha Gogaihur (mm434)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Slt No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	S/R ✓
c)	Riding Quality	✓/R
d)	Road Camber	✓/R
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes No N/A
g)	Compaction of flank/slope & raincuts if any	Yes No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SKR N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR N/A
c)	Condition of railings/slab/approach for Bridges	S/SR N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

—

—

U

Rampreet Choudhary

Rampreet Choudhary
17.12.2020
J.E.
(Signature)