

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020		District: Jaishali	
Division : Hapur		Length (km): 0.790	
Name of the Road: Digghi Paschmi Jogi baba to chakbijagui			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: <input checked="" type="checkbox"/> Ongoing/ <input checked="" type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance	
Work is a case of:		New Connectivity/ <input checked="" type="checkbox"/> Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	✓
b)	Condition of Surfacing	S/U	✓
c)	Riding Quality	S/U	✓
d)	Road Camber	S/U	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
Compliance History			
a)	Status of ATR's & any others		ND

Overall Rating :

Satisfactory (S) ✓	SRI	NOT
Satisfactory but requires Improvement (SRI) ✓		
Unsatisfactory (U)		

Main Information board is

Sanjay
14.12.2020

(Signature)

NAME:

DESIGNATION: