FIELD INSPECTION REPORT

Date of I	aspection :	16/12/2020	District: Bhoifum	The second secon
Division	: PIR	the state of the s	Length (km): 1.535	
Name of	the Road:	Englishbur	To Englishow Ahirpa	Hi
Scheme/	Programme:	MAINTENANC		
Package	No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
St. No.		Parameter	to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			√\$/U
b)	Condition of Surfacing			√8/U
c)	Riding Quality			L8/U
q).	Road Camber			~8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
I)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No
g)	Compaction of flank/slope & raincuts if any Yes/No			Yes/No
2	Cross Drains	ige		
a)	Condition of	head walls in Hum	e pipe culverts including its painting	~8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			/5/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnit	are		*** *********************************
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Cempliance	History		
a)	Status of ATI	R's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Im	provement (\$RI)
Unsatisfactory (U)	

(Signature)

NAME: Vionesh Chandlony J.E

(i)	Rectification done or Not?	_
(ii)	Work Started or Not?	
(iii)	Notice issue by PIU or Not?	_
(iv)	Rectification Started or Not?	_
(v)	Comment if Any?	
(vi)	Grade	
(vii)	Upload image (max 5 image)	Yes
(viii)	Upload inspection Report PDF format	Yes

Tilppoo