## FIELD INSPECTION REPORT

Date of Inspection: - 17.12.20		<b>a</b>	District: - kishanganj		
Division: - Kiphanyanj-I		L	Length(km):		
Name of	the Road: - PMG	SY road T	o NavaToli under GTSNY		
Scheme/	Programme: G	rsny			
Package	No.: N.A		Road Id No.: 2120 5801850		
	the Project: On	going/Complet	ted /Under Maintenance		
Work is	a case of:	<b>ŵ</b> Connectivity	/ Up gradation / Maintenance	T	
\$1. No	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction Condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√\$/U	
d)	Road Camber			√\$/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			-∕Yès/No	
	in case of CC Pavement.			12.	
f)	Contraction Joints Provided or not ( CC Pavement)			√Yes/No	
g)	Compaction of flank / slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			√S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			√S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			√s/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓Yes/No	
4.	Compliance History				
a)	Status of ATR's & a		ATR verivication inspection how	e been done	

## Overall Rating :

Satisfactory(S)	-5-
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory(U)	_

NAME: Radhertyon przejapati

R.W.D (W) Division Kishanganj-1