## FIELD INSPECTION REPORT

Block-Jala/pur

Date of Inspection: 17.12.2020			District: chaforg (	Saran	
Division: chappeg-2			Length (km): 0.700 km		
Name of the Road: 5013 to Madhopur Kotheyem.					
Scheme/Programme: MAINTENANCE					
Package No.: Road Id No.:					
			d/Under Maintenance ✓		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
SI No.		Parameters to	be checked	Remarks	
1.5	Pavement		急数1000000000000000000000000000000000000	排化。 注:	
a)	Road Junction	√S/U			
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√ S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			_Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	√Yes/No			
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			/s/sri/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4-	Compliance H	listory	A THE STATE OF THE		
a)	Status of ATR's & any others			NO ATR	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mituijay Kuman

DESIGNATION: (J.E)