FIELD INSPECTION REPORT

Date of Inspection :	District: Salar
Name of the V	Dodapie 2 Longth (km): 0.9 ro K. rs
Scheme/Programme:	MAINTENANCE POGSY to Dhank pr
Package No.:	67-5-N.
Status of the Project:	Road Id No.:
W	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

CONTRO	The second secon	WHI IS
1	Placement.	
a)	Road Junction condition	∕\$/U
b)	Condition of Surfacing	8/U
c)	Riding Quality	8/U
d)	Road Camber .	8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Ð	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	TO THE THE
n)	Condition of head walls in Hume pipe culverts including its painting	CODIA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	S/SRM
B)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/N
	Compliance History	
1)	Status of ATR's & any others	and the 1
	Past	NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (STR)	
Unsatisfactory (U)	1

NAME: .

DESIGNATION:

(Signature) 17-12-20

Banaba

17/13/2