piprahi

## FIELD INSPECTION REPORT

ate of Inspection: 17.12.2020		District:- Sheohar.		
Division:-RWD, Works Div. Sheohar  Name of the Road:- Ram Dayal Ram ke G		Length (km):- 0.960 KM		
Division	Sthe Bood: Ram Dayal Ram Ke Gh	arto Gachhitola	(G.T.S.N.	Y)
Name of	Programme:- MAINTENANC	CE		
Scheme				
Package	110.:-	Road Id No.: Under Maintenan	ce	1
	TT.	n gradation/ Maint	enance	1
			Remarks	·
Sl. No.	Pavement			
1.	Road Junction condition	S/U	1	
<u>a)</u>			√S/U	
<u>b)</u>	Condition of Surfacing			
<u>c)</u>	Riding Quality		S/U	
<u>d)</u>	Road Camber		√S/U	
<b>e</b> )	Whether free from defects such	Ves/No		
	exposed aggregates in case of CC Pa			
f)	Contraction Joints provided or not (CC Pavement)		Ves/No	
g)	Compaction of flank/slope & raincu	✓Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts S/SRI/U			
	including its painting			
<b>b</b> )	Condition of Abutments & Wing w	alls, Slab in RCC	S/SRI/U	
	culverts		N·A·	
c)	Condition of railing/slab/approach	for bridges	S/SRI/U N·	A
3.	Road Furniture			
a)	Whether sing board/informatory/c		Ves/No	
	Km & 200m stones/Pavement ro	oad marking are		
	provided and maintained		-	
4.	Compliance History			
a)	Status of ATR's & any others	N	any A.T.R.	ir
		Cal	ome.	

Overall Rating :

Satisfactory (S)	451
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Sudhir Kumar

(Signature)

DESIGNATION:- A.E.