	FIELD INSPECTION REPORT	
ate Of	rispection: [4/12/10] District: Simon	
vivision:	Mahrajganj Length: 0.485 KM	
Name O	the Road: To 1 Ra ancest Field	
scheme/	Programme: GITSN7	
Package	No.: Road Id No.:	
Status O	f the Project : Ongoing/Completed/Under Maintenance	
Work is	a case of : New Connectivity/Up gradation/ Mair	tenanco
SI. No.	Parameters to be Checked	Remarks
1	Pavement	Kellidiks
a)	Road Junction condition	S/W
b)	Condition of Surfacing	5/18
c)	Riding Quality	S/M
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	8/SRI/W
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	-
a)	Status of ATR' s & any others	No
-,		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

ANAND KUMAR

DESIGNATION:

AE

(Signature)

MANISH KUMAR OJHA (J.E.)