FIELD INSPECTION REPORT

		r ir.tay iyot ix.			
Date of Inspection: 18-12-20 District: Muzefferpur					
Division: Mag tacker			District: Mysefferfur Length (km): 0 111 1414	1.8 kg	
Name of	the Road: Dag	unaty Pakeri chows	neto Chaphaz gram in Jagarha	th Sanke-ghow	
	rogramme:	MAINTENANCE			
Package No.:			Road Id No.:		
		Ongoing/Completed	d/Under Maintenance		
			tivity/Up gradation/ Maintenance Arms to be sheeked Remarks		
Sl. No.	Parameters to be checked			ICemur KS	
1.	Pavement				
a)	Road Junction condition			SAU	
b)	Condition of Surfacing			,Ş/U	
c)	Riding Quality			SAU	
d)	Road Camber			\8/U	
c)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.				
ŋ	Contraction Joints provided or not (CC Pavement) Yes/No				
g)	Compaction of flank/slope & raincuts if any Yes/No				
2.	Cross Drainage				
	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
a)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U				
b)					
c)	Condition of railings/slab/approach for Bridges S/SRI/U				
3.	Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/No				
a)	Whether sig	Yes/No			
4.	Compliance	,			
a)	Status of AT	R's & any others			

Overall Rating :

Satisfactory (S)	' S`
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Onsatisfactory (0)	

(Signature)

NAME: Behandary

DESIGNATION: Sk.