

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020
 Division : BANKA-2
 District : BANKA
 Name of the Road: Bhagalpur-Dumka Road to Bela (MUKSY, NDB ERICS)
 Scheme/Programme: MAINTENANCE, 2nd year
 Length (km): 0.708
 Package No.:
 Status of the Project: Road Id No.: 20703601905
 Work is a case of: Ongoing/Completed/Under Maintenance ✓
 New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :
 Satisfactory (S) _____
 Satisfactory but requires Improvement (SRI) SRI
 Unsatisfactory (U) _____

Not :- Road Junction has been damaged due to heavy loaded vehicle at initial point
 16-12-2020
 (Signature)

NAME: AJAY KUMAR
 DESIGNATION: AE