FIELD INSPECTION REPORT

Date of Inspection: 17-12-2020			District: Kishanganj		
Division:Kishanganj-1			Length(km): 1.000		
Name	of the Road: PM	1GSY to Musa	Iman tola		
	e/Programme:	GTSNY			
Packag	e No.:		Road Id No.:		
Status of the Project: O		Ongoing/Completed /Under Maintenance			
Work is	s a case of:	New Connectivi	ty/ Up gradation / Maintenance		
\$1. No	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction Condition			SAU	
b)	Condition of Surfacing			√8/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pa	vement.			
f)	Contraction Joints Provided or not (CC Pavement)				
g)	Compaction of flank / slope & rain cuts if any				
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts — NA			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges — NA			S/SRI/U	
3.	Road Furniture				
a)	Whether sign b	Yes/No			
	stones/Pavement road markings are provided and maintained				
4.	Compliance His	tory			
a)	Status of ATR's	& any others			

Overall Rating:

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

NAME: RAMANUJ KUMAR
Designation: Assistant Engineer
RWD Sub Division: Bahadurganj