## FIELD INSPECTION REPORT

Date of Inspection: 17.12.20		District: Muzfforbuz
Division: Echat.	-1	Length (km): 0.460
Name of the Road:	.033 to Chhau	upatting surdanpur
Scheme/Programme:	MAINTENANCE	GT.S.N.Y
Package No.:		Road Id No.: 31507201833
Status of the Project:	Ongoing/Complete	ed/Under Maintenance
Work is a case of:		/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	✓ S/U		
b)	Condition of Surfacing	√ S/U		
c)	Riding Quality	√S/U		
d)	Road Camber	√S/U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N.A	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	LS/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) SRI Unsatisfactory (U)

NAME: Rakesh Kermar Rausham

(Signature)

DESIGNATION: JE