

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020	District: Sagar (Chapra)
Division : Masohara	Length (km): 0.800 k.m.
Name of the Road: Mohamud Puri Lalpur PHGSY Path Se Hospital (Mamang)	
Scheme/Programme: MAINTENANCE ✓	Road Id No.:
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	Complete
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	Yes/No (partly)
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No (partly)
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Flank damage due to flood water.

(Signature) 17/12/20

NAME:

DESIGNATION: