## FIELD INSPECTION REPORT

Block - Jalalpur

			1010	
		7.12.2020	District: Chapra (	Saran)
Division		129-24	Length (km): 1.525	Km ,
		adhai this hot	e bye pastachim to	Koyan tolo
Scheme/Programme: MAINTENANCE 0				
Package No.:		Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sli No.		Parameters to	BEET AND SECTION OF THE PARTY O	Remarks
1.	Payement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			✓S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
. 25	Cross Drainago			的对形法
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	re		A Ministry
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NO ATR

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

NAME: Mintunjan Kuman DESIGNATION: (J.E)