


FIELD INSPECTION REPORT

Date of Inspection:-		District:- Sheohar.	
Division:-RWD, Works Div. Sheohar		Length (km):- 0.833 Km	
Name of the Road:- khatapur PWD road to Badwarathpur (west side)			
Scheme/Programme:-		MAINTENANCE	
Package No.:-		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		~S/U
b)	Condition of Surfacing		~S/U
c)	Riding Quality		~S/U
d)	Road Camber		~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N/A
b)	Condition of Abutments & Wing walls, Slab in RCC culverts		S/SRI/U N/A
c)	Condition of railing/slab/approach for bridges		S/SRI/U N/A
3.	Road Furniture		
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Name:- Rakesh Kumar


 (Signature)

DESIGNATION:- Junior Engineer