## FIELD INSPECTION REPORT

Distate	of Inspection :	1/12/2020	District: East champare	m. motiho
Colonia	" LUCYKS T	William Day	denoth (low): 1 1-2 - 4	
	e/Programme:	In Imala	Y Tola To Geghai To	do
Package Na.:		MAINTENANCE	MMCqSy (S-C)	
Status	of the Project:	Ongoing/Complete	od/Under Maintenance	
Work	is a case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No			Parameters to be checked	
1.	Pavement			100000000000000000000000000000000000000
a)	Road Junction condition			VS/U
b)	Condition of Surfacing			A STOCK III
c)	Riding Quality			↓S/U
d)	Road Camber			US/U
u)			LSNI	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Ves/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			~S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U A
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			_Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: Symwar Alon

DESIGNATION: JE, Potani