

GTSNY

FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020 District: Patna
 Division: Basch Length (km): 0.590 km
 Name of the Road: Kabirchak PMGSY Road to Bigha
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Upgradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SI
b)	Condition of Surfacing	✓ SI
c)	Riding Quality	✓ SI
d)	Road Camber	✓ SI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Completion of flank slope & caments if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pre-culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S SRI U
c)	Condition of railings slab/approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any other-	

Overall Rating : Satisfactory (S) Satisfactory but requires Improvement (SRI) " SRI " Unsatisfactory (U)

24/16.12.2020
 (Signature)

NAME: DHANANJAY KUMAR NIRALA
 A-E