

FIELD INSPECTION REPORT

Date of Inspection: 17/11/2020		District: Muzaffarpur	
Division: RAO East-1 Muzaffarpur		Length (km): 0.416	
Name of the Road: PH-6 by Shikil Praija path to Praija Mahatola.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project: ☒ Ongoing ☐ Completed ☐ Idle ☐ Maintenance			
Work is a case of: ☐ New Connectivity ☐ Up gradation ☒ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒
b)	Condition of Surfacing	☒
c)	Riding Quality	☒
d)	Road Camber	☒
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes ☐ No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes ☐ No
g)	Compaction of Bank/slope & raincuts if any	☒ Yes ☐ No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ SRI ☐ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ SRI ☐ U
c)	Condition of railings/slab approach for Bridges	☒ SRI ☐ U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes ☐ No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Kamlesh
17/12/2020

(Signature)

A.R.W.
Kudhri

NAME:

DESIGNATION:

12/12/2020
J.E