


FIELD INSPECTION REPORT

Date of Inspection : 16.12.20		District: MUZAFFARPUR
Division : MUZAFFARPUR East-1		Length (km): 0.647 K.m
Name of the Road: L069 Bariyarpurkandh to Gaurihar Khalik Nagar to Raytola (Gauriharbang)		
Scheme/Programme: MAINTENANCE		MMG.Sy Gen)
Package No.:		Road Id No.: 31507201280
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA } S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


16.12.20

(Signature)

NAME: Rakesh Kumar Roushan

DESIGNATION: J.E