(21)

FIELD INSPECTION REPORT

					i .
Date of Inspection :	6.12.20	District:	Muzfar	sw.	1
Division: Muzfferpuz East		Length (km): 1.916		1010	
Name of the Road:	Hyazpur Kandh to	Shahpur	Junaid (To	114'ya Chowk tosh	Paswan to Le
Scheme/Programme:	MAINTENANCE		16.5y (sc		Din hourin
Package No.:		Road Id N	0.: 31507	201323	
Status of the Project:	Ongoing/Completed	l/Under Main	ntenance		

Status of	the Project:	Ongoing Completed Order Waintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.	nil	Parameters to be checked	Remarks	
1.	Pavement		and the A	
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality			
d)	Road Camber		_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction	Yes/No		
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drain	nage		
a)	Condition of	Ş/SRI/U		
b)	Condition o	S/SRI/U		
c)	Condition o	S/SRI/U		
3.	Road Furn	iture		
a)	Whether si stones/Pave	Yes/No		
4.	Complianc			
a)	Status of A	TR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

16:12:20

(Signature)

NAME: Railcesh Kumar Raushan

DESIGNATION: JE